# Fire Alarm and Life Safety System Inspection Certificate

For

Parkwood Square B 5880 38th Avenue North St. Petersburg, FL 33710

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Annual Inspection Inspection Date Aug 4, 2025

> Building: Parkwood Square B Contact: Gloria Reed Title: Property Manager

Company: Dart Electronics, Inc.
Contact: Will McGrath
Title: Inspector

Fire Alarm Testing Report

## **Executive Summary**

Generated by: BuildingReports.com

Fax:

**Building Information** 

Building: Parkwood Square B Contact: Gloria Reed

**Address:** 5880 38th Avenue North **Phone:** 727-726-8000 x504

Address:

City/State/ZIP Code: St. Petersburg, FL 33710 Mobile:

Country: United States of America Email: GReed@ameritechmail.com

Inspection Performed By

Company: Dart Electronics, Inc. Inspector: Will McGrath

Address: 5390 Park Blvd N Phone: 727-544-8564
Address: Fax:

City/State/ZIP Code: Pinellas Park, FL 33781 Mobile:

Country: United States of America Email: service@dartelectronicsinc.com

System Control Unit

Manufacturer: Fire-LiteInspection Date: 08/04/2025IDC Style: BModel Number: MP12Install Date: 01/01/1900SLC Style:Software Version:Version Date: 08/19/2022NAC Style: Y

**Location:** 1st Electrical Room Current Protection:

Monitoring

Company: Digicom Monitoring Phone: 1-800-282-5456 Account #: 08-01-0441

Central Station Signal Verification

Type: Digital Radio Mfg: AES Model #: 7788F

Test Time/Date: 8/4/25 11:49:50 AM Restore Time: Note:

Inspection Summary								
Catamamii	Total Items		Serviced		Passed		Failed/Other	
Category:	Qty	%	Qty	%	Qty	%	Qty	%
Auxiliary	2	10.00%	2	100.00%	2	100.00%	0	0.00%
Control	5	25.00%	5	100.00%	5	100.00%	0	0.00%
Indicating	6	30.00%	6	100.00%	6	100.00%	0	0.00%
Initiating	7	35.00%	7	100.00%	6	85.71%	1	14.29%
Totals	20	100%	20	100.00%	19	95.00%	1	5.00%

## Certification

Company: Dart Electronics, Inc. **Building:** Parkwood Square B

Inspector: Will McGrath Contact: Gloria Reed

#### Will McGrath Certifications

Certification Type	Number
FASA / FIRE ALARM SYSTEM AGENT	

## Discrepancy Report

Generated by: BuildingReports.com

#### Building: Parkwood Square B

#### Control Panel: 1 - Fire-Lite MP12

The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is subject to a recall or part of a manufacturer's replacement/upgrade program is included.

<b>Device Type</b>		Manufacturer	ModelNumber	Date		Qty	
Items listed for Recall or Replacement/Upgrade							
	No items found during this inspection.						
ScanID	Location	F	Problem	Address Reference			
	Initiating						
Pull Station							
3 78563929	1st By 111		Can't open the levice	1-1			

# **Proposed Solutions Report**

Generated by: BuildingReports.com

#### Building: Parkwood Square B

Control Panel: 1 - Fire-Lite MP12

The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.

ScanID	Location	Solution	Model #	Cost	Fix
		Initiating			
Pull Station					
78563929	1st By 111	Replace	S270	T/M	
		Customer WO/PO #: (none)	Internal WO/PO #: (none)	T/M	

# Inspection & Testing

Generated by: BuildingReports.com

#### Building: Parkwood Square B

#### Control Panel: 1 - Fire-Lite MP12

Download Date: 08/05/2025

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location		Service	Time	Date
		Passed			
Auxiliary					
Surge Protector	1st Electrical Room		Tested	11:49:02 AM	08/04/2025
Transformer	1st Electrical Room		Tested	11:49:07 AM	08/04/2025
Control					
Annunciator	1st Electrical Room		Tested	11:49:19 AM	08/04/2025
Battery	1st Electrical Room		Tested	11:48:58 AM	08/04/2025
Battery	1st Electrical Room		Tested	11:49:45 AM	08/04/2025
Communicator	1st Electrical Room		Tested	11:49:50 AM	08/04/2025
Control Panel	1st Electrical Room		Tested	11:48:54 AM	08/04/2025
Indicating					
Horn	1st By 111		Tested	11:52:19 AM	08/04/2025
Horn	2nd By 201		Tested	11:58:07 AM	08/04/2025
Horn	2nd By 211		Tested	11:54:49 AM	08/04/2025
Horn	3rd By 301		Tested	11:57:02 AM	08/04/2025
Horn	3rd By 311		Tested	11:55:12 AM	08/04/2025
Horn/Strobe	1st By 101		Tested	11:58:54 AM	08/04/2025
Initiating					
Pull Station	1st By 101		Tested	11:59:00 AM	08/04/2025
Pull Station	2nd By 201		Tested	11:58:02 AM	08/04/2025
Pull Station	2nd By 211		Tested	11:54:43 AM	08/04/2025
Pull Station	3rd By 301		Tested	11:57:25 AM	08/04/2025
Pull Station	3rd By 311		Tested	11:55:24 AM	08/04/2025
Smoke Detector	1st Electrical Room		Tested	11:50:08 AM	08/04/2025
Device Type	Location		Service	Time	Date
		Failed/Other			
Initiating					
3 Pull Station	1st By 111		Tested	11:54:09 AM	08/04/2025

# Service Summary

Generated by: BuildingReports.com

## Building: Parkwood Square B

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
	Failed/Other	
Pull Station	Tested	1
Total		1

	Passed	
Annunciator	Tested	1
Battery	Tested	2
Communicator	Tested	1
Control Panel	Tested	1
Horn/Strobe	Tested	1
Horn	Tested	5
Pull Station	Tested	5
Smoke Detector	Tested	1
Surge Protector	Tested	1
Transformer	Tested	1
Total		19
Grand Total		20

## **Auxiliary Functions Testing**

Generated by: BuildingReports.com

### Building: Parkwood Square B Control Panel: 1 - Fire-Lite MP12

The Auxiliary Functions Testing section lists each of the ancillary items, systems, and emergency equipment that are controlled by the system control unit. Items are grouped by Passed or Failed/Other. The items are listed by device type, and a check box is provided to indicate if the test conducted was simulated.

Туре	Location		Comment	ScanID	Simulated
		Passed			
Surge Protector					
	1st Electrical Room		Passed	78563841	
Transformer					
	1st Electrical Room		Passed	78563843	

# Battery & Power Supply Testing

Generated by: BuildingReports.com

#### Building: Parkwood Square B

Control Panel: 1 - Fire-Lite MP12

Download Date: 08/05/2025

The Battery & Power Supply Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.

Туре	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
Battery		'					
Passed							
Sealed Lead Acid	1st Electrical Room	8	12				
Sealed Lead Acid	1st Electrical Room	8	12				

## **Inventory Report**

Generated by: BuildingReports.com

## Building: Parkwood Square B

#### Control Panel: 1 - Fire-Lite MP12

Download Date: 08/05/2025

The Inventory Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided.

Device or Type	Category	% of Inventory	Quantity
Annunciator	Control	5.00%	1
Battery	Control	10.00%	2
Communicator	Control	5.00%	1
Control Panel	Control	5.00%	1
Horn	Indicating	25.00%	5
Horn/Strobe	Indicating	5.00%	1
Pull Station	Initiating	30.00%	6
Smoke Detector	Initiating	5.00%	1
Surge Protector	Auxiliary	5.00%	1
Transformer	Auxiliary	5.00%	1

## Zone Address Report

Generated by: BuildingReports.com

#### Building: Parkwood Square B

#### Control Panel: 1 - Fire-Lite MP12

The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.

Address	Device Type	Location	Туре	ScanID
Zone/Circu	ıit: 1			
	Pull Station	1st By 111	Single Action	78563929
	Pull Station	2nd By 201	Single Action	78563925
	Pull Station	2nd By 211	Single Action	78563922
	Pull Station	3rd By 301	Single Action	78563918
	Pull Station	3rd By 311	Single Action	78563921
Zone/Circu	nit: 2			
	Smoke Detector	1st Electrical Room	Photoelectric	78563844